HAER NJ 9-**Jer**cy 18K-

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

Colgate & Company Jersey City Plant: B-9 (Colgate-Palmolive Company Jersey City Plant: B-9) 34-40 Crand Street Jersey City Hudson County New Jersey HAER No. NJ-71-K

Photographer: Cerald Weinstein

July - September 1988

- NJ-71-K-1 SOUTH ELEVATION
- NJ-71-K-2 UPPER LEVELS OF EAST SECTION, TO SOUTHWEST: No. 1 STILL AT LEFT CENTER; WOODEN LYE TREATMENT TANK AT UPPER RICHT CENTER; CRUDE LYE SETTLING TANK UPPER CENTER; PART OF No. 3 STILL AT LOWER RICHT
- NJ-71-K-3 PART OF WEST SECTION, TO SOUTH, AFTER PARTIAL DECONSTRUCTION: SEPARATOR AT UPPER CENTER; TWO EVAPORATORS AT CENTER AND LOWER CENTER (LATTER PARTLY CUT AWAY)
- NJ-71-K-4 EAST SECTION LOFT, TO SOUTHWEST
- NJ-71-K-5 FILTER PRESSES UNDER ROOF OF WEST SECTION, TO SOUTHWEST
- NJ-71-K-6 DUMP CAR APPARATUS UNDER ROOF OF WEST SECTION, TO SOUTHWEST

KEY TO PHOTOGRAPHS

COLGATE & COMPANY JERSEY CITY PLANT: B-9

(Colgate-Palmolive Company Jersey City Plant: B-9)

HAER No. NJ-71-K

(Page 2)

